# AB 885 Policy on Septic Systems

June 19, 2012





- the Policy still needs:
  - provisions for detecting failing <u>existing</u> high- & moderate-risk systems
  - incentive for timely TMDL development & compliance
  - a numeric nitrogen limit for large systems

- the Policy still needs:
  - provisions for detecting failing <u>existing</u> high- & moderate-risk systems
  - incentive for timely TMDL development & compliance
  - a numeric nitrogen limit for large systems

#### **Pumper Reports**

Goal- to detect failing existing systems:

Upon pumping, the Service Provider shall evaluate the OWTS to determine the condition of the system, including but not limited to, the condition of the tank, signs of surfacing and any repairs or upgrades required to ensure that existing systems are functioning properly and provide a report to the owner and Local Agency.

Signature of Qualified Inspector:

EHS 42-12 (Rev. 7/04)



#### County of Santa Barbara Septic Tank Inspection Report

( Please Print or Type )

Deportment 9	icte Stamp

			Phone	Phone No.:		
Location of inspection: -		( ADDRESS)		(CITY)	(ZIP)	
No. of Bedrooms:	Year Septic System Built:		t			
Septage disposal location	1 / date:					
System Components:						
Estimated capacity of sep	otic tank or cess	pool: gal	k With Seepage Pit (Hollo . No. of compartments:	Amount pumper	dga	
		to Access Lids: _	Diameter of A	ccess Lids:		
Construction of septic tan Rectangular Concrete	A STATE OF THE PARTY OF THE PAR	Other Plastic	☐ Brick ☐ Other			
Condition of tank: Tank deteriorated Baffle wall deteriorated Lids are deteriorated Heavy grease build-up		Yes	Inlet tee present Outlet tee present House lateral open Needs pumping	No Yes		
Minimum concrete thickne	ess of tank top, r	measured at lids:	Method	of Measurement:		
Prior to pumping, was effl	luent level above	outflow tee?	No Yes (may indi	cate failing system)		
Signs of surfacing effluent	t? No Ye	es, location:				
Any signs of past drainag	e problems? 🗌	No Yes		Site Map		
Maintenance Performed:				ing to		
	actioning satisfar	rtorily? No 🗆 Ve	se D	11 1		
Sustem annears to be fun	ichounily across	Money: No La re		I have a		
		-14-4				
Repairs / upgrade require		side) No 🗆 Ye	86 🗌		7	
Repairs / upgrade require		side) No 🗌 Ye			II.	
Repairs / upgrade require 1. 2.		side) No 🗆 Ye	96		$\langle\!\langle$	
System appears to be fun Repairs / upgrade require 1. 2. 3 Comments / Recomment	ed? (see reverse			COP	< Placeholder</td	
Repairs / upgrade require 1 2 3	dations:			COP	1	
Repairs / upgrade require 1 2 3 Comments / Recomment Did a Qualified Inspector	dations:			COP	<b>√</b>	

Date:

Phone:

## Tier 0 – Moderate-Risk Existing OWTS

• Why is threshold 10,000 gpd for existing systems?

"Experience shows that larger OWTS (greater than 3,500 gallons-per-day) are more likely to fail than smaller ones and are best limited to design flows of less than 6,000 gallons-per-day (Plews et al. 1985)."

-- From Attachment 2: Scientific Assumptions, Findings and Conclusions to be Addressed by Peer Reviewers.

#### Tier 3 – Impaired Areas

Advanced Protection Management Programs for Impaired Areas

• Existing, new, and replacement OWTS that are near impaired water bodies may be addressed by a TMDL and its implementation program, or special provisions contained in a Local Agency Management Program. If there is no TMDL or special provisions, existing, new, or replacement OWTS within 600 feet of impaired water bodies listed in Attachment 2 must meet the applicable specific requirements of Tier 3.



- the Policy still needs:
  - provisions for detecting failing <u>existing</u> high- & moderate-risk systems
  - incentive for timely TMDL implementation & <u>compliance</u>
  - a numeric nitrogen limit for large systems

#### Timeline Of TMDL Implementation

**Furthest deadline Last TMDL OWTS** no longer for Regional implementation contribute to **Boards to draft Policy AB 885** actions begin impairments becomes law adopted **TMDLs** 2??? 1999 2012 2025 2022 SCHOOL BUS R.I.P

## Preamble TMDL Compliance Deadlines

#### Attachment 2

 Tables 4 and 5 specifically identify those impaired water bodies that have Tier 3 requirements and must have a completed TMDL by the date specified, and the TMDL must set an implementation schedule to meet waste load allocations within 10 years of the specified date.

#### Tier 3 – Impaired Areas

• 10.3 If a TMDL for the impaired waterbodies identified in Attachment 2 is not in effect within five years of Policy adoption, OWTS will undergo an inspection within the sixth year by a qualified professional to verify the system is not failing or contributing to the impairment. If the system is found to be a failed OWTS and/or contributing to the impairment, the OWTS will upgrade to Advanced Treatment within 1 year. Inspections shall occur every 3 years if no TMDL comes into effect in the interim.



- the Policy still needs:
  - provisions for detecting failing <u>existing</u> high- & moderate-risk systems (>3,500 gpd)
  - incentive for timely TMDL <u>compliance</u>
  - a numeric nitrogen limit for large systems (>3,500 gpd)

#### Tier 3 – Impaired Areas

- 10.9.1 Effluent from the supplemental treatment components designed to reduce nitrogen shall be certified by NSF, or other approved third party tester, to meet a 10 mg/L limit in total nitrogen for commercial properties discharging over 3,500 gpd when comparing the 30-day average influent to the 30-day average effluent.
  - 10.9.1.1 For commercial properties discharging over 3,500 gpd, when 10mg/L limit is not achievable, the OWTS owner shall apply for a WDR.



Table 2. Selected Performance of Residential Nutrient Reduction Technologies

Vendor and	Average Total Nit	% Reduction <sup>c</sup>		
Model*	Influent	Effluent	70 T CCGGOTTOTT	
Α	36	15	58%	
В	37	14	62%	
С	39	14	64%	
D	37	15	59%	
E	39	19	51%	
F	37	16	57%	

A Because the ETV Program does not compare technologies, the performance results shown in this table do not identify the vendor associated with each result and are not in the same order as the list of technologies in Table 1.

### U.S.EPA Environmental Technology Verification Program: Residential Nutrient Reduction

B mg/L as N = milligrams per liter as nitrogen


<sup>&</sup>lt;sup>c</sup> Table in Metcalf and Eddy shows the following values of nitrogen reduction using older technologies: Total Nitrogen Raw 35-80 mg/L and effluent of septic systems, 25-60 mg/ L, corresponding to 25 - 30 % removal. These numbers show that the new ETV technology is an improvement - doubling previous removal rates.

#### Other Concerns...

## **Density Revision**

Table 1. Allowable average densities per subdivision under Tier 1.

Average Rainfall	Allowable Density
	(acres/single family
<u>(in/yr)</u>	<u>dwelling unit)</u>
<u>0 - 15</u>	<u>2.5</u>
<u>&gt;15 - 20</u>	<u>2</u>
<u>&gt;20 - 25</u>	<u>1.5</u>
<u>&gt;25 - 35</u>	<u>1</u>
<u>&gt;35 - 40</u>	<u>0.75</u>
>40	0.5



#### Strengthening Clarifications

- 9.1 "Where different and/or additional requirements are needed to protect water quality the local agency shall consider any of the following, as well as any other conditions deemed appropriate, when developing Local Agency Management Program requirements…"
- 9.1.12 Geographic areas that are known to have multiple, existing OWTS located within either the pertinent setbacks listed in Section 7.5 of this Policy, or a more conservative setback that the local agencies finds is appropriate for that area.

#### Depth to Groundwater

#### Tier 2

9.4.8 Separation of the bottom of dispersal system to groundwater less than  $\frac{1}{2}$  five (5) feet, except for seepage pits, which shall not be less than 10 feet.

#### **Conditional Waiver**

• 12.0.2 The OWTS shall not utilize a dispersal system that is in soil saturated with Groundwater, nor shall the separation of the bottom of a dispersal system to groundwater be less than five (5) feet.

## Thank you